



SPECIFICATIONS

Range	: 0~5000g
Tare	: Unlimited
Negative weight	: Tare Function will set negative weight to 0 without add-on.
Tare upon turning on	: Allow tare up to max tare upon turn on
Accuracy	: ± 1 % of reading
Calibration	: Four points of Automatic Calibration at 0g, 1600g, 3200g and 4800g
Load Cell Technology	: 5000g Compact Loadcell
Resolution	: 1g step
Minimum Weight	: >1g
Min. Add-on Wt.	: >1g
Power	: AC Adaptor: 9 V, 100mA (Supplied) Battery: 9 V alkaline cell (Not supplied)

Warm-up time : 3 seconds or less.
Display : Four Digit LCD
Display after warm-up : 0
Auto Off : Auto off after 5 min. of no Load Change or Key Pressed.
Display Features : Overload → "EE"
Low Power : 7V ± 0.3V
Temperature : Good performance within -10 degree Centigrade to +45 degree Centigrade.
Case & Platform : Fine texture ABS plastic.


PHYSICAL FEATURES

Dimensions : 20cm X 14.5cm X 5.5cm
Platform Size : 11.5cm x 14cm, Fold up platform for weighing large letters
Weight : 1lb 0.23oz (460g) without Batteries

KEYS

ON/TARE : Scale ON and/or for setting the container weight to zero
OFF : Scale OFF

KEYBOARD LAYOUT



XIAR